

July 1, 2020

To whom it may concern


NELES VALVGUARD VG800 LIFE CYCLE STATUS CHANGE TO OBSOLETE

In the beginning of 2010, we released a new version of Neles ValvGuard VG9000 to sales. This new version replaced the previous generation Neles ValvGuard VG800. After the sales release of VG9000, the VG800 life cycle status was changed to 'Support' status. Further on, at the beginning of 2015, the life cycle status of VG800 was changed to 'Limited support' status as announced in January 2015. Since then there were only spare parts available, but not new devices anymore.

Now the VG800 life cycle status is changed to 'Obsolete'. It means that we do not have the spare parts available anymore. VG800 has been fully replaced with VG9000.

In case you have any questions on the life cycle status of the VG800, on VG800 replacement cases or on the current VG9000, please don't hesitate to contact the undersigned or the local Neles sales office.

Yours sincerely,



Janne Laaksonen
Senior Product Manager